

# Repair Quote # C051441

## CUSTOMER

Ken Vincke  
ZF Active Safety US Inc.  
500 E. Van Riper  
Fowlerville, MI 48836

PO # : na

## Instrument Information

Instrument : ATEQ Premier F  
Serial Number : E173-0126

## ATEQ Corp.

Technician : Ricky Staten  
Date Of Repair : 03-Feb-2017

### DEFAULT FOUND BY THE CUSTOMER

Will not attain pressure - Calibrate.

### DEFAULT FOUND BY ATEQ/DEFECT

Solenoid leaking. Fill valve leaking. Valve contamination. Keyboard poly not working.

### WORK PERFORMED

Calibration

### WARRANTY

Not under warranty

### DETAIL OF WORK

Replaced solenoid. Replaced fill valve. Replaced front keyboard poly. Rebuilt valve. Calibrated. Tested with no faults found.

### SPARE PARTS UTILIZED

ATEQ Code	DESCRIPTION	Price	Discount	QTY	Ext Price
0528945US	F3 High Speed Fill valve	110.0000	0	1.0	110.00
042974X-R	Solenoid for Y- Valve (Refurbished)	30.0000	0	1.0	30.00
Labour	In house labour / hour	105.0000	0	4.0	420.00
Cal Inst.	Calibration Instrument	240.0000	0	1.0	240.00
F5MINIKIT1	F5 Mini-Valve Kit #1	50.0000	0	1.0	50.00
9530118	S5 front keyboard poly	45.0000	0	1.0	45.00

Total () :

895.00

A surcharge fee of 2.5% will be applied to all credit card transactions.  
SERVICE WARRANTY: 6 months parts and labour from date of service.

## ATEQ Corp.

35980 Industrial Road - Livonia, MI 48150-1274

T.: 734-838-3100 - F.: 734-838-0644 - serviceorders@atequsa.com - atequsa.com

A Member of ATEQ World-wide Group of Companies

